ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0606, W0961, W0612, W0610, W0967, W0618, W0616	NA, 3rd Crs	Bhuvaneshwarinagara 20 R Cross
Segment No.	**Total Length (m)**	
6/C-W0606/S031410	114.05	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	69.09	77.606467	13.054530	77.607087	13.054388	Bhuvaneshwarinagara 20 R Cross	cross road
2	22.48	77.606955	13.054826	77.607159	13.054791	Bhuvaneshwarinagara 20 R Cross	cross road
3	22.48	77.606955	13.054826	77.607159	13.054791	Bhuvaneshwarinagara 20 R Cross	cross road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains (Concrete drain) and comprehensive development of roads from 12th A Cross to 20th R Cross at Bhuvaneshwarinagara near Coffee bo	20000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		006-19-000031
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/254/2018-19	02/03/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/03/2019	02/03/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

KRIDL		0.00
Phone No.	**E-Mail ID**	
9900333496		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
0		suresh devath raj
Date of Inspection	**Remarks**	
03/03/2020		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	04/03/2020	02/04/2020	As proposed
SE	Vijay Kumar Haridas	03/03/2020	02/04/2020	Forwarded
EE	Mohandas H.T	03/03/2020	02/04/2020	approved
AEE	Sridhar B.S	03/03/2020	02/04/2020	Mobile vefication is done
AE	Suresh Devathraj	03/03/2020	02/04/2020	Mobile verification is done
AE	Suresh Devathraj	03/03/2020	02/04/2020	Forwarded

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0606, W0961, W0612, W0610,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	**Ward No.**	**Ward Name**
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0961	NA	Bhuvaneshwarinagara 20th R Cross
Segment No.	**Total Length (m)**	
6/S-W0961/S031850	174.47	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	174.47	77.607038	13.053892	77.607290	13.055450	Bhuvaneshwarinagara 20th R Cross	main road

Work Details

History of Road / Lane / Circles		
Name of the Work	**Sanctioned Estimated Amount (Rs.)**	**Sanctioned Year**
Improvements to drains (concrete drain) and comprehensive development of roads from 12th A Cross to 20th R Cross at Bhuvaneshwarinagara near coffee bo	20000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender		006-19-000031
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/254/2018-19	02/03/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/03/2019	02/03/2020	No

Contractor Details

Name of Contractor	**Contractor Reg No (BBMP/PWD)**	**Expenditure Booked \ Released (Rs)**
KRIDL		0.00
Phone No.	**E-Mail ID**	
9900333496		

ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-24

Field Inspection Details

Number of Trees	Any Other Information	Name
0		suresh devath raj

Date of Inspection	Remarks
03/03/2020	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	04/03/2020	02/04/2020	As proposed
SE	Vijay Kumar Haridas	03/03/2020	02/04/2020	Forwarded
EE	Mohandas H.T	03/03/2020	02/04/2020	approved
AEE	Sridhar B.S	03/03/2020	02/04/2020	verified
AE	Suresh Devathraj	03/03/2020	02/04/2020	Mobile verification is done
AE	Suresh Devathraj	03/03/2020	02/04/2020	Forwarded